Accelerator Division Safety Procedure

ADSP-02-0101

Response to Violations of the Accelerator Safety Envelope

Responsible Department: ESH&Q RPE

Prepared By:

____ Date <u>3-27-2017</u>

ESH&Q Radiation Physics Engineering Department Head

Reviewed By: AD RSO Date 3/27/2017

AD RSO V Reviewed By: AD Operations Department Head Approved By: Accelerator Division Head Date 3/27/17 Date 3/25/17

Revision No. 4 Revision Issue Date 3 -27-17

Table of Contents

1.0	Purpose and Scope2
2.0	Responsibilities2
2.1	Accelerator Division Head2
2.2	ESH&Q Radiation Physics Engineering Department Head2
2.3	AD Operations Department Head3
2.4	AD Operations Crew Chief3
3.0	Immediate Response to Violations3
3.1	Beam Transport without an Operational Radiation Safety Interlock System
3.2	Less than the Minimum Number of Operating Personnel on Shift
3.3	Beam Transport without an Authorized Beam Permit & Running Condition3
3.4	Exceeding Beam Intensity and/or Energy Limits Prescribed on Beam Permits and Running
Conditions	
3.5	Response to Potential ASE Violations3
3.6	Initiating Occurrence Reporting4
3.7	Resuming Accelerator Operations4
4.0	Distribution4

1.0 Purpose and Scope

This procedure establishes the response to be taken by the Accelerator Division (AD) following the discovery of a potential Accelerator Safety Envelope (ASE) violation.

The ASE is the Department of Energy (DOE) "Authorization Basis" under which Fermilab may operate its accelerator facilities. The ASE is derived from the Fermi National Accelerator Laboratory Safety Assessment Document (SAD) and defines the operating conditions, safe boundaries, surveillance requirements, and the management or administrative controls necessary for safe operations that reduce the risk to the public, Fermilab workers, or the environment from accelerator operations.

The ASE requires that Radiation Safety Interlock System be functional during beam operations, accelerator operations be approved by the Accelerator Division Head, minimum staffing requirements be met in the Main Control Room (MCR), and beam operations occur within the established intensity and energy limits. The Beam Permit and Running Condition documents are used to convey to the Operations Department the ASE and maximum authorized operating intensity limits associated with each accelerator or beamline area.

2.0 Responsibilities

2.1 Accelerator Division Head

- Responsible for determining whether an apparent violation is a violation of the ASE.
- Responsible for ensuring that the appropriate steps have been taken such that, if a violation of the ASE has occurred, the complex has ceased to operate outside of the ASE.
- Responsible for informing the Facility Manager as defined in FESHM 3010.
- Responsible for coordinating the follow-up assessment of the incident, with particular emphasis on assessing the impact of the excursion on people and the environment.
- Responsible for determining whether operation may resume and is responsible for authorizing such resumption if a violation has not occurred or, following consultation with the Chief Safety Officer and Director, if a violation has occurred.

NOTE: Any activity violating the ASE must be terminated immediately, and the activity must not recommence before the DOE Fermi Site Office has been notified.

2.2 ESH&Q Radiation Physics Engineering Department Head

- Responsible for ensuring the preparation and maintenance of this procedure.
- Responsible for reporting violations of the ASE in accordance with the Fermilab ES&H Manual.

2.3 AD Operations Department Head

• Is responsible for instructing the Operations Department Crew Chiefs and Operators on the requirements of this procedure.

2.4 AD Operations Crew Chief

• The Crew Chief is responsible for implementing the immediate response to potential violations of the ASE. The crew chief should, in all cases as a first response, use his/her best judgment in taking reasonable actions to return the complex to a safe operating condition.

3.0 Immediate Response to Violations

The following sections outline possible violations of the ASE and the required response to these violations.

3.1 Beam Transport without an Operational Radiation Safety Interlock System

The Radiation Safety Interlock System shall have no known loss of safety function in any section where beam operations are in progress.

3.2 Less than the Minimum Number of Operating Personnel on Shift

To ensure robust knowledge of accelerator systems during both normal and off-normal machine operations, there shall be no less than one qualified member of the Operations Department who has achieved the rank of Operator II or higher on shift. There shall be no less than one member of the Operations Department present in the Main Control Room during beam transport operations.

3.3 Beam Transport without an Authorized Beam Permit & Running Condition

The AD will not transmit beam without an authorized Beam Permit and Run Condition specifying the beam power equivalent limitations.

3.4 Exceeding Beam Intensity and/or Energy Limits Prescribed on Beam Permits and Running Conditions

To ensure that off-normal machine operations do not produce accident conditions greater than 500 mrem per hour, beam intensities in each portion of the accelerator are monitored. The ASE limit on the Beam Permit and Run Condition documents specifies the maximum beam intensity and energy.

- 3.5 Response to Potential ASE Violations
 - a. Crew Chief will disable beam to all accelerator areas.

- b. If the ASE violation is a beam intensity excursion, the Crew Chief shall have the area outside the affected beamline visually surveyed for personnel. Any personnel in the area shall be identified by name with contact information for further follow-up.
- c. Crew Chief shall inform the following individuals:
 - i. Accelerator Division Head;
 - ii. AD Operations Department Head;
 - iii. ESH&Q Radiation Physics Engineering Department Head;
 - iv. AD Radiation Safety Officer;
 - v. AD Run Coordinator if applicable.
- d. The Accelerator Division Head will determine whether the apparent violation has indeed occurred, and whether it violates the ASE.
- e. The Accelerator Division Head, following appropriate consultation, will determine whether there were any beam-related losses associated with the violation.
- f. The Accelerator Division Head will determine whether the beam losses, if they occurred, produced radiation that exceeded levels allowed in the FRCM.
- g. At the direction of the Accelerator Division Head, information will be gathered on the operational conditions at the time of the violation as necessary.

3.6 Initiating Occurrence Reporting

In the event it is determined that a violation of the ASE has occurred, the responsibility for reporting violations resides with the Accelerator Division Head.

NOTE: If the Accelerator Division Head determines that the potential violation does not constitute a violation of the ASE, no further reporting is required.

3.7 Resuming Accelerator Operations

The Accelerator Division Head has the authority to allow resumption of operations as long as the ASE has not been violated. Prior to allowing the resumption of operations, the Accelerator Division Head, in conjunction and consultation with others as necessary and appropriate, must analyze the excursion, assess its ES&H impact, and determine that appropriate steps have been taken such that subsequent excursions are unlikely.

The Accelerator Division Head has the authority to allow resumption of operations following an ASE violation, having considered the impact of the excursion on people and the environment, after consultation with the Chief Safety Officer, Director, and DOE Fermi Site Office.

4.0 Distribution

An electronic controlled copy of this procedure is maintained on the ES&H Department web site at: <u>http://ad-esh.fnal.gov/ad_adsp.html</u>