

## ACCELERATOR DIVISION SHELTER LOCATIONS

February 22, 2016

Building/Area	Shelter Area
Preaccelerator and Linac Areas, West Booster Gallery, West Booster Portakamps, West Booster Towers, and MuCool Test Area	Proceed to the lower level of the Linac and Preaccelerator areas. Take cover in the Linac or Cross Gallery lower level or in the Preaccelerator lower level area.
Cross Gallery, Transfer Gallery, East Booster Gallery, East Booster Tower, AØ Complex, and F4 Portakamps	Take cover in the utility tunnels beneath the Cross Gallery or the Transfer Gallery or in the staging area beneath the Cross Gallery.
BØ Power Supply/Compressor Building	If conditions permit, cross over the berm, enter CDF and take shelter in the CDF stairwell (below grade); otherwise, take cover in the Power Supply Room.
CØ Shops/Compressor Room and Portakamps	Take cover in the vestibule of the north CØ building exit (formerly the stairwell down to MR tunnel).
CØ Assembly Building (Remote Handling Facility)	Take shelter in the lower level of the stairwell.
DØ MVA and Power Supply/Compressor Building	Take cover in the stairwell leading down to the DØ tunnel entrance.
EØ Power Supply/Compressor Building and Portakamps	Take cover in the EØ minor vehicle access tunnel.
Tevatron Service and Refrigerator Buildings	Take cover in the Tevatron Controls Room inside the Service Building.
Main Ring Kicker Buildings, F17, F23, and F27 Power Supply Buildings	Take cover inside building against rear wall (closest to the berm).
Tevatron Enclosure, Booster Enclosure, Anti-Proton Source (Muon) Enclosures, Switchyard Enclosures, 8 GeV Line, Main Injector Enclosure, NuMI Pre-Target Enclosure, and NuMI Target Hall	Stay underground. Take cover in a connecting corridor or in the corridor leading to the nearest exit or service building or in portions of beam line enclosures which contain low levels of residual radioactivity. Move away from those portions of the enclosures where radiation levels are high.
Switchyard Service Building	Take cover in the stairwell leading to the Switchyard enclosure.
G2 Service Building	Take shelter in the vestibule entrance leading to the F1 enclosure.

Building/Area	Shelter Area
F0 Service Building	Take shelter in the F0 tunnel access stairwell or proceed to MI-60 and take shelter in the MI-60 tunnel access stairwell.
MI-60 Service Building	Take shelter in the MI-60 tunnel access stairwell.
MI-8 Service Building	Take shelter in the MI-8 tunnel access stairwell.
MI-10, 14, 20, 30, 39, 40, 50, 52, and 62 Service Building	Take shelter in the hallway leading from the back of the service building to the tunnel access door. (If in MI-14 or 39, proceed to the MI-10 or 40 shelter area, respectively.)
MI-11 and 21 (Peanuts)	Remain in the underground room.
MI-12 (MiniBooNe)	Take shelter in the stairwell leading down to the MiniBooNe enclosure.
MI-31 (Pelletron)	Take shelter in the restroom in the Control Room .
MI-65 (NuMI)	Utilize the corridor between the electronics room and the fire command room as the tornado shelter.
E4R Test Area	Take cover in the concrete hoops or in the E4 Service Building in the Tevatron Controls Room.
Antiproton Source Buildings (Muon Campus)	<p>Take shelter in entry vestibules of the AP10, AP30, or AP50 Antiproton Service Buildings or the North entry vestibule of APØ Target Service Building.</p> <p>If there are too many people seeking shelter to be reasonably accommodated in the vestibules, emergency access can be gained to additional shelter space by following the steps below to enter the tunnel enclosure stairwells.</p> <p>Pull the plastic cover off the key box located at the entrance to each of the stairwells to the Antiproton rings or the stairwell at the north end of APØ. Remove key (interlocked) and open door to interlocked enclosure. Take cover in stairwell below ground level. <b>Do not proceed into the tunnel but remain in the stairwell.</b></p>

Building/Area	Shelter Area
Meson Cryo Central Building, Meson Cryo Portakamps, MS4, MS5, MS6, and Meson Detector Building Areas	Take shelter in restrooms on east and west sides of Meson Detector Building.
MW9	Take shelter in the MW8 tunnel (entrance at the south end of MW9) or in the kitchen or restrooms in office area.
NWA and Portakamps	Take shelter in the Test Cave inside NWA. If cave door is closed, use Emergency Breakout Panel to reach door lever and open door. Opening door will break the cave interlocks.
NML	Take shelter in restrooms or the lower level of the stairwells.
Cryo Module Test Facility (CMTF) and Compressor Room	Take shelter in CMTF restrooms.
NML Electrical Service Building	Take shelter in NML or CMTF shelter areas.
MS1, 2, and 3	Take shelter in restrooms.
MS7	Take shelter in restrooms in southeast corner of MP9.
NS1, 2, 4, and 7	Take shelter in restrooms.
NS3	Take shelter in restrooms in Operations Center.
Target Service Building (TSB)	Occupants of TSB should remain in TSB.
PS1, 2, 3, 4 and 6	Take shelter in stairwells to enclosure.
PS5	Take shelter in Restrooms in Operations Center.
External Beamline Enclosures	Take cover in a connecting corridor or in the corridor leading to the nearest exit or service building or in portions of beam line enclosures which contain low levels of residual radioactivity. Move away from those portions of the enclosures where radiation levels are high.
Central Helium Liquefier Building	Take shelter in the tech shop washrooms in the southeast corner of main building on the first floor.
36 Sauk (Old Fire Barn or Materials Development Lab)	Closest shelter is located at 21 Sauk, Dorm 3.

Building/Area	Shelter Area
IARC / OTE	Take shelter in lower levels of HAB stairwells.
IARC / HAB	Take shelter in lower levels of HAB stairwells.